

HAM0061738\_0001

IMAGE 1

Dan Mike

Fr Dec 14/18

Look at PW 18-008

→ Notes friction testing    Connect w  
Available                      - Byrdena  
→                                      - Ludimor?


Check P.O on Golders Nov 18  
Assignment

→ Genesis of Proposal

Make this a PW-18-008b

INFO Report: PW Report Jan <sup>28</sup> (14/18)

→ Staff are performing tasks

→ MFIPPA  = Access to INFO

→ Resurfacing/Functional

→  Priority Road

INFO UPDATE 18-008 will be updated

→ Identified issues in 18-008

Advance of report

To ensure public safety

HAM0061738\_0001

Report to Council?

Nov 27/18

2013/14 – Golders Draft  
Review

Dan  
Gord  
Gary

2017 CTAA H-I-P in Halifax

Check 10 yr forecast but when added

MTO was using GMA in 2007

- Higher skid apparently
- Better Spray
- Gap Graded mix / Drains [water]

2007 results

2012 – 23

Anecdotal – Proactively want out

Different method than the MTO method  
was a UK study

Report told him to do more testing

Nov 17 Do PSV – From Ireland ←  
Tyler or Rick ←

\* Orig Material came from Dufferin ([Llyod Ferg])

Sold material as Spect'd by Golder

MTO Regional Director →