

Message

From: Rabiah_Rizvi@golder.com [Rabiah_Rizvi@golder.com]
Sent: 12/19/2017 3:17:04 PM
To: Amelia_Jewison@golder.com
Subject: RE: RHVP Report
Attachments: E303.6599.pdf; nchrp_rpt_634appendixes.pdf; FINAL GUIDE - DEC 2013.pdf

The ASTM for the British Pendulum testing is attached. Also attached to this email are two references that you can use to find out more information on the testing and analysis of the results.

Rabiah Rizvi (P.Eng.) | Pavement and Materials Engineer | **Golder Associates Ltd.**
6925 Century Avenue, Suite #100, Mississauga, Ontario, Canada L5N 7K2
T: +1 (905) 567 4444 | **D:** +1 (905) 567-6100 x2310 | **F:** +1 (905) 567 6561 | **C:** +1 (519) 590 3442 | **E:**
Rabiah_Rizvi@golder.com | www.golder.com

Work Safe, Home Safe

This email transmission is confidential and may contain proprietary information for the exclusive use of the intended recipient. Any use, distribution or copying of this transmission, other than by the intended recipient, is strictly prohibited. If you are not the intended recipient, please notify the sender and delete all copies. Electronic media is susceptible to unauthorized modification, deterioration, and incompatibility. Accordingly, the electronic media version of any work product may not be relied upon.

Golder, Golder Associates and the GA globe design are trademarks of Golder Associates Corporation.

Please consider the environment before printing this email.

From: Jewison, Amelia
Sent: Tuesday, December 19, 2017 9:26 AM
To: Rizvi, Rabiah <Rabiah_Rizvi@golder.com>
Subject: RHVP Report

Hi Rabiah,

I have a couple more questions about the Red Hill Valley Parkway project. Will the Whitby lab be able to extract the aggregates this week or should I be arranging the for them to get shipped to Ireland in the new year? What should I be doing with the British Pendulum data? Also, do you know of a similar report that I could use as a template for this one?

Thanks,
Amelia

Amelia Jewison (B.A.Sc., EIT) | Geotechnical Analyst | **Golder Associates Ltd.**
6925 Century Avenue, Suite #100, Mississauga, Ontario, Canada L5N 7K2
T: +1 (905) 567 4444 | **D:** +1 (905) 567-6100 | **F:** +1 (905) 567 6561 | **C:** +1 (519) 494 1882 | **E:** ajewison@golder.com |
www.golder.com

Work Safe, Home Safe